


# Restoration Sites and Wetland Impairment in Barrington, Rhode Island



<b>Adjacent Degradation Source</b> Cropland Dairy Farm Erosion & Sedimentation Golf Course Industrial Plant Impervious Surface Sand/Gravel Operation Lawn Landfill Excavated		<b>Restoration Type</b> Artificial Reef Salt Marsh Seagrass (Eelgrass) Anadromous Fish Habitat Grassland Riverine Floodplain Shellfish/Water Quality	Primary Roads Streams Ponds   Scale = 1:50,000
--	--	---	---

Source: Wetland data were produced by the Narragansett Bay Estuary Program through aerial photo interpretation. All other data layers were produced by the University of Rhode Island's Environmental Data Center.

