


Restoration Sites and Wetland Impairment in Little Compton, Rhode Island



Adjacent Degradation Source		Restoration Type			
	Cropland		Artificial Reef		Primary Roads
	Dairy Farm		Salt Marsh		Streams
	Erosion & Sedimentation		Seagrass (Eelgrass)		Ponds
	Golf Course		Anadromous Fish Habitat		
	Industrial Plant		Grassland		
	Impervious Surface		Riverine Floodplain		
	Sand/Gravel Operation		Shellfish/Water Quality		
	Lawn				
	Landfill				
	Excavated				

0 0.5 1 Kilometers
 0 0.5 1 Miles
 Scale = 1:80,000

Source: Wetland data were produced by the Narragansett Bay Estuary Program through aerial photo interpretation. All other data layers were produced by the University of Rhode Island's Environmental Data Center.